03500.005745.38 <u>PATENT</u>

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
		:	Examiner: Mariceli Santiago
SEISHIRO YOSHIOKA ET AL.)	
		:	Art Unit: 2879
Appln. No.: 09/587,249)	
		:	Conf. No.: 6842
Filed: June 2, 2000)	
		:	
For:	DISPLAY DEVICE WITH ELECTRO	N-)	
	EMITTING DEVICE WITH ELECTRO	ON-:	
	EMITTING REGION INSULATED)	
	FROM ELECTRODES	:	
)	
U.S. Patent No.: US RE40,062 E		:	
)	
Issued:	February 12, 2008	:	August 4, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached.

The amount of \$100.00 to cover the statutory fee for such Certificate of Correction is being paid concurrently; please charge any deficiency in this fee, and credit any overpayment, to Deposit Account 06-1205.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Frank A. DeLucia/
Frank A. DeLucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

2242901v1

Staple Here Only! Staple NINE S'ABLNING

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US RE40,062 E

DATED

February 12, 2008

INVENTOR(S) :

SEISHIRO YOSHIOKA ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) REFERENCES CITED

After "Energy Distribution": "J, Trickl," should read -- J. Trickl,--;

After "Water-Influenced": "(Mar. 1984))." should read --(Mar. 1984).--;

After "C.A. Spindt,": "et al." should read --et al.,--; "Thin-Film" should read --Thin-Film field--; and

After "T. Izumiya et al.,": "Kokai Butsuri," should read --"Kokai Butsuri,"--.

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"44-27852 * 11/1944" should read --44-27852 * 11/1969--.

COLUMN 1

Line 31, "1965." should read --1965).--.

COLUMN 4

Line 8, "state;" should read --state.--;

Line 9, "cross sections" should read --cross-sections--;

Line 10, "8;" should read --8.--; and

Line 13, "invention;" should read --invention.--.

COLUMN 5

Line 3, "state; and" should read --state.--;

Line 4, "device" should read --device.--; and

Line 5, "partially" should read --a partially--.

MAILING ADDRESS OF SENDER:

PATENT NO. US US RE40,062 E

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

No. of add'l. copies

@ 30¢ per page

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US RE40,062 E

DATED

February 12, 2008

INVENTOR(S) :

SEISHIRO YOSHIOKA ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 39, "FIG. 2" should read --FIG. 2.--; and Line 54, "be also" should read --also be--.

COLUMN 7

Line 55, "be also" should read -- also be--.

COLUMN 9

Line 60, "spacing 1." should read --spacing L.--.

COLUMN 10

Line 10, "be also" should read -- also be--.

COLUMN 14

Line 35, "photolithography" should read --photolithoetching--.

COLUMN 49

Line 48, "3 a" should read --3a--.

COLUMN 20

Line 27, "be also" should read --also be--; and Line 32, "be also" should read --also be--.

MAILING ADDRESS OF SENDER:

PATENT NO. US US RE40,062 E

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

2242901v1

⊏'>

Stable Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US RE40,062 E

DATED

February 12, 2008

INVENTOR(S) :

SEISHIRO YOSHIOKA ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22

Line 66, "sheet" should read --sheets--.

COLUMN 23

Line 1, "to the" should read --to the second--; and Line 30, "(see" should read --(See--.

COLUMN 26

Line 12, "less" should read --less.--.

COLUMN 27

Line 32, "(%)" should read --(%).--; and Line 47, "less" should read --less.--.

COLUMN 30

Line 46, "illustrate" should read --illustrates--.

COLUMN 32

Line 31, "kind" should read --kinds--; and Line 40, "a" (second occurrence) should read --an--.

MAILING ADDRESS OF SENDER:

PATENT NO. US US RE40,062 E

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

(212) 210 2200 10

Form PTO 1050 (Rev. 3-82)

2242901v1



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US RE40,062 E

DATED

February 12, 2008

INVENTOR(S) :

:

SEISHIRO YOSHIOKA ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 33

Line 23, "mount" should read --amount--.

COLUMN 39

Line 8, "insulated" should read --insulating--.

MAILING ADDRESS OF SENDER:

PATENT NO. US US RE40,062 E

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

No. of add'l. copies @ 30¢ per page

(212) 218-2200 - Facsimile